




Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /  
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /  
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /  
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb /  
 Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /  
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu







XX = AA

Position








- 1 = H 961 943 NU
- 2 = H 961 493 NU
- 3 = H 961 944 NU
- 4 = H 961 945 NU
- 5 = H 961 946 NU
- 6 = H 961 947 XX
- 7 = H 961 936 NU

OLD VERSION



**CONNECT**  
**N 1396 ..**

0811 / H 965 755 - 2  
 (+ A 865 612)  
 Made by JADO in E.U.



Ideal Standard International BVBA  
 Chaussée de Wavre, 1789 - box 15  
 1160 Bruxelles  
 Belgium

[www.idealstandardinternational.com](http://www.idealstandardinternational.com)

